

---

## **Servicii de reparatie videoproiector Sanyo PLC-XP100L cu nr. de inventar 321689**

I.D.: 42860117

---

Data publicarii	22.05.19	Coduri CPV	50800000-3
-----------------	----------	------------	------------

---

Pretul estimativ:	1.638,66 RON - 1.638,66 RON
-------------------	-----------------------------

---

Descriere: Servicii de reparatie videoproiector Sanyo PLC-XP100L cu nr. de inventar 321689 : - lampa videoproiector Sanyo PLC-XP100L - curatire

---