

Remediere defectiuni SV18SCB

I.D.: 45189452

Data publicarii	16.03.20	Coduri CPV	50113000-0
-----------------	----------	------------	------------

Pretul estimativ:	1.904,62 RON - 1.904,62 RON
-------------------	-----------------------------

Descriere: Efectuare test scurt Verificare retarder hidrodinamic Verificare si constatare instalatie electrica calculator retarder Resetare coduri erori Releu - 1 buc
