
Servicii de reparare masina de spalat ind.IPSO

I.D.: 76281522

Data publicarii	09.12.22	Coduri CPV	50532000-3
-----------------	----------	------------	------------

Pretul estimativ:	1.185,00 RON - 1.185,00 RON
-------------------	-----------------------------

Descriere: Reparatie masina de spalat rufe industrială IPSO : inlocuit presostat, inlocuit bobina cu electromagnet la vana golire, reparat modul electronic la DGASPC SECTOR 1 / CAR PAD. Milcov str. Milcov nr.2 Bucuresti
