
Reparatii Service BH13RBZ

I.D.: 51138607

Data publicarii	30.10.20	Coduri CPV	50110000-9
-----------------	----------	------------	------------

Pretul estimativ: 1.922,10 RON - 1.922,10 RON

Descriere: Manopera 399.60 (demontat/montat/ inlocuit piese schimb; inspectie service schimb ulei; verificarea eficacitatii franei) piese de schimb 1522.50 (surub, cartus filtru aer/ polen/ ulei, Ulei Castrol, 2 set garnituri frane, materiale mici
