
Reconditionare cartise toner imprimate

I.D.: 44689621

Data publicarii	29.11.19	Coduri CPV	30125120-8
-----------------	----------	------------	------------

Pretul estimativ: 470,61 RON - 470,61 RON

Descriere: 1 Cilindru Xerox 3200/3117/Samsung ML1610 Buc 1,00 2 Cilindru Hp 1005/1505 pentru 35A/36A/CRG728/CRG725 Buc 2,00 3 Chip Xerox 3140 Buc 2,00 4 Pickup Roller Samsung ML 2510, 2570, SCX 4725, Xerox Ph 3200 Buc 1,00 5 Reconditionare cartus laser Samsung ML1610 / ML1615 / ML2010 / ML2570 2k Buc 1,00 6 Reconditionare cartus laser HP 12A 2k HP 1018 Buc 1,00 7 Reconditionare cartus laser HP LaserJet Pro M125NW / M126 / M 27 / M1 HP 83A (CF283A) 1.5k Buc 4,00 8 Reconditionare cartus laser HP P1102/P1002 HP M1130/1132 HP 85A 1.6k Buc 2,00 9 Reconditionare cartus laser HP P1102/P1002 HP M1130/1132 HP 85A 1.6k Buc 2,00 10 Reconditionare cartus laser Xerox 3140 2.5K Buc 2,00 11 Inlocuire rola de preluare hartie H 0,50 12 Reconditionare cartus laser Samsung ML1610 / ML1615 / ML2010 / ML2570 2k Buc 1,00
