



Servicii de reparatie uscator de rufe

I.D.: 47309934

Data
publicarii 15.06.20

Coduri CPV 50800000-3

Pretul
estimativ: 330,00 RON - 330,00 RON

Descriere: Servicii de reparatie uscator de rufe: - inlocuire pompa de apa - 1 buc - deplasare,
contatare, manopera schimbare pompa de apa
