
reparatie auto polo

I.D.: 85812738

Data publicarii	09.08.23	Coduri CPV	50112000-3
-----------------	----------	------------	------------

Pretul estimativ: 1.415,50 RON - 1.415,50 RON

Descriere: Servicii intretinere la vehicul Volkswagen Polo -inlocuit ulei si filtre (ulei,aer,habitaclu,combustibil) -inlocuit ventilator radiator si releu ventilator -inlocuit conector teava esapament
