
Reparatie la statia de includere la parafina Histostar

I.D.: 81457098

Data publicarii	28.04.23	Coduri CPV	50421000-2
-----------------	----------	------------	------------

Pretul estimativ: 3.795,00 RON - 3.795,00 RON

Descriere: Reparatie la statia de includere la parafina Histostar: 1. A81010047 SOLENOID VALVE KIT - pret 2115 lei 2. A81030053 Garnitura valva solenoid - pret 280 lei 3. Interventie service la cerere la Statie includere in parafina HISTOSTAR-HS3284A1512 - pret total 1400 lei
