



Reparatie Stihl Motocoasa FS 360 C-E

I.D.: 84371588

Data
publicarii 04.07.23

Coduri CPV

50800000-3

Pretul
estimativ: 481,34 RON - 481,34 RON

Descriere: Stihl Autocut 25-2-1 buc,70.16806 lei Stihl Placa 41167103800-1 buc,79.8319 lei Stihl Filtru
41481410300-1 buc,28.403 lei Stihl Arbore 41487113202-1 buc,163.025 lei Stihl Tub
41487117301-1 buc,39.075 lei lucrari reparatie-100.840 lei
