
SERV INTRETINERE UTILAJE SI CAMIOANE (REVIZIE OBLIG LA REPREZ/ INTERVENTII COMPLEXE NEPREZ

I.D.: 94683984

Data publicarii	14.03.24	Coduri CPV	50110000-9 50114000-7
-----------------	----------	------------	-----------------------

Pretul estimativ: 20.070,00 RON - 20.070,00 RON

Descriere: Reparatie autoutilitara PRB Mercedes Sprinter CT 14 CUT 1. Furtunuri hidraulice 2SN 8:12 buc; 2. Furtunuri hidraulice 2SN 10 :6 buc; 3. Cuple hidraulice:10 buc; 4.Ulei hidraulic:40 litri 5. Filtru fin de presiune;1 buc; 6. Manopera demontat/inlocuit furtunuri, inlocuit furtun, incarcare ulei, reglaje si probe functionale.
