
REPARATIE SISTEM IDSAI - Tulghes

I.D.: 97714789

Data publicarii	24.05.24	Coduri CPV	31625200-5
-----------------	----------	------------	------------

Pretul estimativ: 2.970,00 RON - 2.970,00 RON

Descriere: NR Echipament Descriere Cant. P.U. VALOARE 1 Acumulator PL7 2 100.00 200.00 2 Camera ANHD bullet de exterior, 2MP, IR 60m, lentila fixa 2.8mm, , WDR 130dB, 3D/2D DNR, BLC, HLC +video balun 3 300.00 900.00 3 Detector fum 2 180.00 360.00 4 Sursa de alimentare 1 150.00 150.00 5 Cablu incendiu 35 3.00 105.00 6 Cablu efracție 35 3.00 105.00 7 Materiale marunte 1 100.00 100.00 TOTAL MATERIALE/ECHIPAMENTE [LEI fara TVA] 1920.00 "Manopera instalare echipamente : -schimbare Acumulatori PL7 defecti -schimbare Camere video defecte -schimbarea detectorilor defecti; - schimbarea sursa defecta; -recablare camera video -recablare si refacere bucla detectori" 1 1050 1050 - DEPLASARE / CAZARE / DIURNE 1 0 TOTAL GENERAL [lei fără TVA] 2970.00 TVA [19%] 564.30 TOTAL [lei cu TVA] 3534.30
