
Reparat pompa Lowara 2,2kw

I.D.: 44559245

Data publicarii	22.11.19	Coduri CPV	50532100-4
-----------------	----------	------------	------------

Pretul estimativ: 1.984,00 RON - 1.984,00 RON

Descriere: Demontat pompa,efectuat constatare si schema de bobinaj,extras bobinajul vechi,spalat,curatat,confectionat izolatie si bobine,introdus bobinele in stator,efectuat conexiuni,consolidat bobinajul,impregnat,curatat de lac dupa impregnare,inlocuit presetupa,inlocuit rulmentii 6204,reparat turbine,montat,probat.
