
REPARATII POMPE

I.D.: 97365246

Data publicarii	15.05.24	Coduri CPV	50511000-0
-----------------	----------	------------	------------

Pretul estimativ: 6.080,00 RON - 6.080,00 RON

Descriere: -PRELUCRARI AXURI POMPE WILO;prelucrari mecanice sudura +strung+freza -REPARATII POMPA HCP PUMP:sudare cuplaj fonta ,frezat -REPARATII POMPA WILO : rebobinare motor ;inlocuire rulmenti; -REPARATII POMPA FLYGT : rebobinare ;lucrari mecanice conexe; inlocuire rulmenti;presutupa Flygt ; -REPARATII POMPA JUNG UAK 35/2 B2 :rebobinare ; inlocuire rulmenti;inlocuire presutupe; lucrari mecanice conexe ; -REPARATII POMPA HOMA TP 50M 37/2D :lucrari mecanice conexe
