
SERVICII REPARATIE CUTIE VITEZE TRACTOR SAME EXPLORER 105.4

I.D.: 80705271

Data publicarii	05.04.23	Coduri CPV	50100000-6
-----------------	----------	------------	------------

Pretul estimativ: 33.216,71 RON - 33.216,71 RON

Descriere: SERVICII REPARATIE CUTIE VITEZE TRACTOR SAME EXPLORER 105.4 Ambreiaj buc 1 Disc ambreiaj buc 1 Furca buc 1 Suport rulment buc 1 Rulment presiune buc 1 Manson rulment buc 1 Ax principal buc 1 Simering buc 1 Manson toba buc 1 Ulei UTTO litru 60 Filtru buc 1 Filtru buc 1 Ulei motor litru 10 Filtru ulei buc 1 Filtru motorina buc 1 Filtru motorina buc 1
