
Reparatie pompa Wilo Helix First V 2212

I.D.: 98675228

Data publicarii	10.06.24	Coduri CPV	50510000-3
-----------------	----------	------------	------------

Pretul estimativ: 7.101,47 RON - 7.101,47 RON

Descriere: Reparatie pompa Wilo Helix First V 2212 (art 4200580/777596), constand din: - schimbarea setului de rulmenti (motor+cuplaj), - schimbarea cartusului de etansare, - manopera aferenta.
