

---

## Sevicii de reparare masina de spalat

I.D.: 43602845

---

Data publicarii	30.08.19	Coduri CPV	50532000-3
-----------------	----------	------------	------------

---

Pretul estimativ: 146,97 RON - 146,97 RON

---

Descriere: Sevicii de reparare masina de spalat Hotpoint Verificare, inlocuit sistem inchidere hublou, reconditionat electrovalva, reglat presostat, deblocat pompa evacuare, probe functionale. Material = 62,97 lei (fara TVA) Tarif = 84.00 lei (fara TVA) Total = 146.97

---