
Reparatii B 82 ACT

I.D.: 71723808

Data publicarii	29.07.22	Coduri CPV	50110000-9
-----------------	----------	------------	------------

Pretul estimativ: 5.830,99 RON - 5.830,99 RON

Descriere: Inloc lampa semnal aripa stg + lampa gabarit cabina, Inloc ulei motor, filtru ulei, uscator si aer, Gresat pivoti, Inloc bara longitudinala directie, Degripat capete bara transversala + piulite, Inloc capete bara transversala stg/dr, Inloc cilindru rabatare cabina, Golit / reumplut inst de racire, Inloc termostat si o-ring, D/R radiatoare racire, Remediat sistem fixare toba esapament, Efectuat reglaj de geometrie directie, Curatat si spalat radiatoare racire CONFORM DEVIZ
