
INLOCUIRE si REPARATIE COMPONENTE CLIMATIZARE

I.D.: 60597718

Data publicarii	03.09.21	Coduri CPV	50730000-1
-----------------	----------	------------	------------

Pretul estimativ: 4.640,00 RON - 4.640,00 RON

Descriere: Interventie de reparatie : inlocuire tavita condens -2 buc ; inlocuire placa de baza ventilconvector 3.7kw arsa / CHILLER MIDEA 65kw ;reparare placa de baza unitate interna si unitate externa ,aparat aer conditionat tip coloana Citizen 12.3kw Manopera 22 ore x 95.00 ron/ora = 2090.00 ron Tavita condens 9-12 2 buc x 300.00 ron/buc = 600.00 ron PUB VTC /3.7kw 1 buc x 650.00 ron/buc = 650.00 ron PUB UI -12.3kw/reparatie 1 buc x 650.00 ron/buc = 650.00 ron PUB UE -12.3kw/reparatie 1 buc x 650.00 ron/buc = 650.00 ron TOTAL = 4640.00 RON
