
Remediere defecte sistem detectie-avertizare la inceput incendiu (hotel&sala de sport)-COMPLEX SILVA

I.D.: 95017405

Data publicarii	22.03.24	Coduri CPV	31625100-4
-----------------	----------	------------	------------

Pretul estimativ: 6.507,00 RON - 6.507,00 RON

Descriere: Pachet remediere defecte sistem detectie-avertizare la inceput de incendiu constand in:
Hotel: detector fum 4 buc; acumulator sursa incendiu 12 buc; acumulatori centrala detectie 2 buc; verificare/testare si repunere in functiune 1 buc. Sala sport: buton manual de incendiu 1 buc; acumulator sursa incendiu 10 buc; acumulatori centrala detectie 2 buc; verificare/testare si repunere in functiune 1 buc.
