

Reparatii auto

I.D.: 6099580

Data publicarii	20.04.15	Coduri CPV	50110000-9
-----------------	----------	------------	------------

Termenul limita pentru depunere:	22.04.15	Pretul estimativ:	10.700,00 RON
----------------------------------	----------	-------------------	---------------

Descriere: Prestarea serviciilor:1. constatare tehnica, reparatii la sistemul de alimentare carburant, sistem directie, sistem franare un autoturism Nissan Terrano, SS VSKTVUR20U0496326, an fabricatie 2002, tip motor Nissan TD27, 92 Kw, estimat 2000 lei;2. constatare tehnica, reparatii sistem transmisie(grup diferential) si sistem alimentare carburant la un autoturism Nissan Terrano, SS VSKTVUR20U0496368, an fabricatie 2002, tip motor Nissan TD27, 92 Kw, estimat 2000 lei; 3. diagnoza computerizata, reparatii la sistemul de alimentare carburant(pompa injectie), planetara stanga fata, bujii incandescente la un autoturism Nissan Terrano, SS VSKTVUR20U0496309, an fabricatie 2002, tip motor Nissan TD27, 92 Kw, estimat 2000 lei; 4. constatare tehnica, inlocuit rulment roata fata stanga la un Nissan Pathfinder, an fabr. 2008, tip motor YD25, 126 kw, SS VSKJVWR51U0340098, estimat 300 lei; 6.constatare tehnica, inlocuit rulmenti roata fata stanga+dreapta la un Nissan Pathfinder, an fabr. 2008, tip motor YD25, 126 kw, SS VSKJVWR51U0340611, estimat 600 lei; 6. diagnoza computerizata, inlocuit kit distributie la un VW Transporter T4, an fabr. 2005, tip motor VW AXL, 75 kw, SS WV2ZZZ70Z2H077933, estimat 1000 lei; 7.diagnoza computerizata, reparat ansamblu acceleratie(pedala acceleratie) la un VW Transporter T4, an fabr. 2005, tip motor VW AXL, 75 kw, SS WV2ZZZ70Z2H090771, estimat 800 lei; 8. diagnoza computerizata, inlocuit kit distributie la doua VW Transporter T4, an fabr. 2005, tip motor VW AXL, 75 kw, SS WV2ZZZ70Z2H087807, WV2ZZZ70Z2H087807 estimat 2000 lei;
