
Reparatie imprimanta XEROX 3315

I.D.: 36678422

Data publicarii	19.06.19	Coduri CPV	50313100-3
-----------------	----------	------------	------------

Pretul estimativ: 100,00 RON - 100,00 RON

Descriere: SCHIMBARE CHIP CARTUS - 2 BUC. (50LEI/BUC.); CURATARE IMPRIMANTA, CURATARE SENZORI HARTIE, CURATARE ROLE PRELUARE HARTIE; CURATARE ROLE PRELUARE HARTIE ADF, CURATARE SCANNER, CURATARE UNITATE DRUM; CURATARE CUPTOR
