
Reparatie pompa SL1.50.65.30

I.D.: 85811288

Data publicarii	09.08.23	Coduri CPV	50511000-0
-----------------	----------	------------	------------

Pretul estimativ: 8.326,98 RON - 8.326,98 RON

Descriere: Lucrari de reparatie pentru electropompa Grundfos tip SL1.50.65.30 care includ: manopera de demontare, constatare defecte si inlocuire piese: kit priza stator 1buc., kit lagare 1buc., kit etansare 1buc., kit garnituri 1buc., ulei ondina 1buc., kit rotor 1buc., rebobinat stator, manopera.
