

Reparatie chiller Clint

I.D.: 98995948

Data
publicarii 18.06.24

Coduri CPV 50700000-2

Pretul
estimativ: 3.085,44 RON - 3.085,44 RON

Descriere: Deplasare, constatare si reparatie chiller Clint (CHA/K/ST 151 CC), constand in incarcare cu freon (9.5 kg). Realizare probe de functionare.
