

---

**Reparatie electropompa SL1.50.65.30.2.50D.C**  
**Model:9862425810000278**

I.D.: 46767990

---

Data publicarii	29.05.20	Coduri CPV	50511000-0
-----------------	----------	------------	------------

---

Pretul estimativ: 5.607,22 RON - 5.607,22 RON

---

Descriere: KIT ETANSARE B/C22 - 1,736.13 RON; KIT O-RING FRAME B - 313.55 RON; SET RULMENTI SE/SL - 330.97 RON; SENZOR UMIDITATE - 586.45 RON; Material marunt (ulei camera etansare, lavete, smirghel, vaselina, vopsea, spray curatare, spray lubrifiere, etc) - 229.84 RON; Rebobinare motor electric P=3 kW aferent electropompa SL1.50.65.30.2.50D.C Model:9862425810000278 - 838.18 RON; Manopera reparatie electropompa SL1.50.65.30.2.50D.C Model:9862425810000278 - 1,572.10 RON

---