
servicii inlocuire fuser unit si Driver Assy Kyocera

I.D.: 62284136

Data publicarii	21.10.21	Coduri CPV	30125000-1
-----------------	----------	------------	------------

Pretul estimativ: 2.875,00 RON - 2.875,00 RON

Descriere: Pachet fuser unit si drum unit-uri Kyocera: - Drive Assy pentru Kyocera P2040 - 1 buc - 375 lei fara TVA/bucata; - Fuser unit Kyocera Ecosys P2040 - FK-1150 230V - 1 buc - 940 lei fara TVA/bucata; - Maintenance Kit MK475 - pentru Kyocera FS6525 - 1 buc - 1560 lei fara TVA/bucata
