

Interventie service-constatare stare tehnica a spectrometrului FT-IR Bruker model TENSOR 37

I.D.: 63569557

Data publicarii	26.11.21	Coduri CPV	50410000-2
-----------------	----------	------------	------------

Pretul estimativ:	3.500,00 RON - 3.500,00 RON
-------------------	-----------------------------

Descriere: Interventie service-constatare stare tehnica a spectrometrului FT-IR Bruker model TENSOR 37, seria i22180 - constatare parte software, hardware (sursa IR, optica, detector)
