
Reparatie EV SX 300 si Dynacord PM 1000 II

I.D.: 42913275

Data publicarii	07.06.19	Coduri CPV	50800000-3
-----------------	----------	------------	------------

Pretul estimativ: 394,96 RON - 394,96 RON

Descriere: Schimbat buton, curatat, verificat, schimbat pasta termica Dynacord PM 1000 II s/n D112926070119610 Reparat difuzor joase EV SX 300 s/n 0212M00684 Capac buton pornire/oprire Intrerupator pornire/oprire Dynacord.
