

---

## Servicii reparatii hidraulice

I.D.: 41736152

---

Data publicarii	03.02.20	Coduri CPV	50100000-6
-----------------	----------	------------	------------

---

Pretul estimativ: 2.100,00 RON - 2.100,00 RON

---

Descriere: Reparatiile hidraulice efectuate sunt: reparat furtun Karcher ( M14 PO+M 14 FE+B DN6/2SN), reparat furtun AGR 32 1.1/4+B, reparat furtun AGR 20 3/4+B ( 3 buc), reparat furtun AGR 25 1", reparat furtun DKR 25 1" ( 2 buc), furtun hidr DN16/2SC+DKR 5/8 PO+AGR 5/8+B L=1.70 ( 2 buc), garnitura cauciuc ( 4 buc), DN12/2SC+ORF 13/16 PO+ORF 1" PO+B L=2.30, montat unitate preparare aer+supapa sens 1/4, DN19/2SC+DKR 1" PO+AGR 1"+B L=2.10, DN10/2SC+DKR 3/8 PO+DKR 3/8 PO+B L=2.50, reparat furtun DKR 12 1/2+B

---