
REPARATIE SALUPA RAPIDA GEOSURVEY 2

I.D.: 68183119

Data publicarii	12.04.22	Coduri CPV	50241000-6 50241200-8
-----------------	----------	------------	-----------------------

Pretul estimativ:	3.000,00 RON - 3.000,00 RON
-------------------	-----------------------------

Descriere: REPARATIE SALUPA RAPIDA GEOSURVEY 2 - 1 x 3000 ron - demontat/remontat trim - inlocuit kit de reparatie trim complet - inlocuit ulei hidraulic 1l
