
Servicii de reparatie si inlocuire subansamblela sonde gama tip HNQ24.

I.D.: 41885956

Data publicarii	01.02.19	Coduri CPV	50800000-3
-----------------	----------	------------	------------

Pretul estimativ:	6.500,00 RON - 6.500,00 RON
-------------------	-----------------------------

Descriere:	1 BUC. Servicii de reparatie si inlocuire subansamblela sonde gama tip HNQ24., PRET MAXIM ACCEPTAT 6500 LEI/BUC
------------	---
