
Reparat aparat sudura electric Minarc 150

I.D.: 63194918

Data publicarii	17.11.21	Coduri CPV	50532000-3
-----------------	----------	------------	------------

Pretul estimativ: 888,56 RON - 888,56 RON

Descriere: Reparatie aparat sudura electric Minarc 150 Piese schimbate si servicii: - Placa electronica set IGBT (componenta electronica a unei placi electronice) x 1 buc. (Cod 4297750) - Colier x 2 buc. (Cod SP9377121) - Manopera service x 2 ore - Constatate service
