
Pachet piese revizie chiller McQuay McSmart 190c

I.D.: 42954893

Data publicarii	07.06.19	Coduri CPV	50730000-1 42530000-0
-----------------	----------	------------	-----------------------

Pretul estimativ: 2.842,00 RON - 2.842,00 RON

Descriere: - schimbat filru ulei ; - curatat cu azot instalatie circuit Freon ; - efectuat vidare instalatie ; - introdus Freon instalatie si ulei compressor ; - verificare instalatie electrica ; - probe de functionare chiller.
