
Reparatie pompa de spalat cu presiune HD 5/15

I.D.: 49640616

| | | | |
|-----------------|----------|------------|------------|
| Data publicarii | 13.09.20 | Coduri CPV | 34913000-0 |
|-----------------|----------|------------|------------|

Pretul estimativ: 559,00 RON - 559,00 RON

Descriere: Oferta neacceptata in termen: Reparatie pompa de spalat cu presiune HD 5/15. Reparatia implica schimbarea urmatoarelor piese de schimb: 6.961-000.0 - Microintrerupator 1 buc, 4.775-463.0 - pistol 1 buc, manopera- 1 buc
