
Achizitie servicii reparatii Dacia Duster

I.D.: 57032785

Data publicarii	18.05.21	Coduri CPV	50100000-6
-----------------	----------	------------	------------

Pretul estimativ: 378,74 RON - 378,74 RON

Descriere: Conditii refuzate: Reparatii auto AR35CMA constand in: inlocuit si echilibrat anvelope, ITP, revizie instalatie electrica, inlocuit bec farH7, bec numar inmatriculare, bec pozitie. In tarif se regaseste manopera si piesele
