

Kit reparatie electropompa Flygt 6020.181

I.D.: 83571147

| | | | |
|-----------------|----------|------------|------------|
| Data publicarii | 16.06.23 | Coduri CPV | 42124000-4 |
|-----------------|----------|------------|------------|

Pretul estimativ: 4.667,00 RON - 4.667,00 RON

Descriere: Kit reparatie electropompa Flygt 6020.181 - Kit etansari mecanice si garnituri - 1 buc,. - 4,050.00 lei; - Kit rulmenti - 1 buc. - 617.00 lei.
