
Servicii de reparatie aparat climatizare DAIKIN

I.D.: 28923878

Data publicarii	15.06.18	Coduri CPV	50730000-1
-----------------	----------	------------	------------

Termenul limita pentru depunere:	21.06.18
----------------------------------	----------

Descriere:	Constatare, inlocuire piese defecte si punere in functiune aparat climatizare split inverter DAIKIN 36000btu, gama professional model RZQ100B9W1 - FHQ100B - BRC1D52 amplasat la obiectivul RADAR Topolog Tulcea. Cod eroare aparat E7.
------------	---
