
Piese imprimante

I.D.: 41401725

Data publicarii	23.01.20	Coduri CPV	30125000-1
-----------------	----------	------------	------------

Pretul estimativ: 3.173,00 RON - 3.173,00 RON

Descriere: Canon IR2520 Camera 109 Hol sn. RML03665 Sistem preluare tava 1 rupt - necesar inlocuire 715lei+TVA Canon IRA6555 Camera 622 sn. SMF04126 Necesari kit reparatie cuptor 1008lei+TVA Canon LBP 6780 Camera 4 Str Traian sn. MXDA142640 Necesari kit role preluare hartie 105lei+TVA Lexmark MX417 Camera 617 nr. 70157PLM1NDZT Necesari kit role preluare hartie DADF 350lei+TVA Canon IRA6555i Camera 317A sn. XQS01309 Necesari kit role preluare hartie 165lei+TVA x 4buc Necesari kit preluare DADF 235lei+TVA Lexmark T642 Camera 613 nr. 7909T82 Necesari kit role preluare hartie 100lei+TVA
