

---

## REPARATIE PERFUSOR SPACE seria 548205

I.D.: 77315848

---

Data publicarii	11.01.23	Coduri CPV	50000000-5
-----------------	----------	------------	------------

---

Pretul estimativ:	1.294,64 RON - 1.294,64 RON
-------------------	-----------------------------

---

Descriere: REPARATIE PERFUSOR SPACE seria 548205 = 1294.64 LEI FTVACOD DESCRIERE CANTITATE (buc.) PRET LEI / buc FARA TVA VALOARE LEI FARA TVA PIESE SCHIMB 34502001 Lump Sum for Consumables (kit pentru reparatii) 1 50.00 50.00 34520970 OPERATING UNIT, COMPLETE PSP (panou operare PSP) 1 834.24 834.24 34774386 COVER CAP CASE SP (capace suruburi echipament SP) 10 1.04 10.40 SERVICII REPARATII MANOPERA REPARATII +CALIBRARE+TSC 1 400.00 400.00 TOTAL DEVIZ FARA TVA = 1294.64 LEI Achizitia din SEAP tine loc de comanda

---