
reparatie perfusoare compact plus 21233 si 20455

I.D.: 81729740

Data publicarii	05.05.23	Coduri CPV	50000000-5 50430000-8
-----------------	----------	------------	-----------------------

Pretul estimativ: 1.467,78 RON - 1.467,78 RON

Descriere: REPARATIE PERFUSOR COMPACT PLUS seria 21233 = 450.00 LEI FTVA PERFUSOR COMPACT PLUS seria 21233 COD DESCRIERE CANTITATE (buc.) PRET LEI / buc FARA TVA VALOARE LEI FARA TVA PIESE SCHIMB 34502001 Lump Sum for Consumables (kit pentru reparatii) 1 50.00 50.00 SERVICII REPARATII MANOPERA REPARATII +CALIBRARE+TSC 1 400.00 400.00 REPARATIE PERFUSOR COMPACT PLUS seria 20455 = 1017.78 LEI FTVA PERFUSOR COMPACT PLUS seria 20455 COD DESCRIERE CANTITATE (buc.) PRET LEI / buc FARA TVA VALOARE LEI FARA TVA PIESE SCHIMB 34502001 Lump Sum for Consumables (kit pentru reparatii) 1 50.00 50.00 34522103 HOUSING, UPPER PART PCP (carcasa - subansamblu superior PCP) 1 567.78 567.78 SERVICII REPARATII MANOPERA REPARATII +CALIBRARE+TSC 1 400.00 400.00
