

Reparatii aparatura BTL in urma reviziei

I.D.: 75430965

Data publicarii	18.11.22	Coduri CPV	34913000-0 31711100-4
-----------------	----------	------------	-----------------------

Pretul estimativ:	18.930,00 RON - 18.930,00 RON
-------------------	-------------------------------

Descriere: 1. BTL 5640 ; SN: 038-B-04722 a) 3 x Buton placa encoder - 3 x 100 RON fara TVA = 300.00 RON fara TVA b) 4 x Cabluri electro gri / alb - 4 x 80.00 RON fara TVA = 320.00 RON fara TVA c) 8 x Electrode 5/7 cm - 8 x 80.00 RON fara TVA = 640.00 RON fara TVA d) 4 x Cablu BTL-5000 cu led - 4 x 250.00 RON fara TVA = 1000.00 RON fara TVA 2. BTL 5640 ; SN: 038-B-04778 a) 3 x Buton placa encoder - 3 x 100 RON fara TVA = 300.00 RON fara TVA b) 4 x Cabluri electro gri / alb - 4 x 80.00 RON fara TVA = 320.00 RON fara TVA c) 8 x Electrode 5/7 cm - 8 x 80.00 RON fara TVA = 640.00 RON fara TVA d) 4 x Cablu BTL-5000 cu led - 4 x 250.00 RON fara TVA = 1000.00 RON fara TVA 3. BTL- 5820SL ; SN: 0381406 a) Cablu sonda ultrasunet - 300.00 RON fara TVA b) 3 x Buton placa encoder - 3 x 100 RON fara TVA = 300.00 RON fara TVA c) 4 x Electrode 5/7 cm - 4 x 80.00 RON fara TVA = 320.00 RON fara TVA d) Sonda laser 830 nm 200 mW - 5000.00 RON fara TVA e) Placa sonda ultrasunet - 300.00 RON fara TVA 4. BTL 5100 ; SN: 038-B-04726 a) Cablu sonda laser - 300.00 RON fara TVA 5. BTL 5820SL ; SN: 0380B009617 a) 3 x Buton placa encoder - 3 x 100 RON fara TVA = 300.00 RON fara TVA b) 4 x Cabluri electro gri / alb - 4 x 80.00 RON fara TVA = 320.00 RON fara TVA c) 8 x Electrode 5/7 cm - 8 x 80.00 RON fara TVA = 640.00 RON fara TVA d) Cablu sonda laser - 300.00 RON fara TVA 6. BTL 5820SL ; SN: 0380B009577 a) 3 x Buton placa encoder - 3 x 100 RON fara TVA = 300.00 RON fara TVA b) 4 x Cabluri electro gri / alb - 4 x 80.00 RON
