
Servicii inlocuire volanta VW Transporter

I.D.: 104116832

Data publicarii	10.10.24	Coduri CPV	50112000-3
-----------------	----------	------------	------------

Pretul estimativ: 11.238,95 RON - 11.238,95 RON

Descriere: Demontat si montat cutie viteza, volanta, tampon, inlocuit capac carcasa cutie, discuri franare fata, rulment intermediar cardan, completat ulei cutie, verificat eficacitate franare, tren de rulare, convergenta fata reglat, masurat autoturism fata-spate.
