
REPARATIE MOTOPOMPA HONDA WB20XT (40824)

I.D.: 87790135

Data publicarii	04.10.23	Coduri CPV	50800000-3
-----------------	----------	------------	------------

Pretul estimativ: 678,60 RON - 678,60 RON

Descriere: INLOCUIT ULEI, INLOCUIT GARNITURA MECANICA (PRESETUPA), INLOCUIT GARNITURI SURUBURI, CURATAT SI REGLAT CARBURATOR, CURATAT FILTRU AER, VERIFICAT SUPAPE, TESTE FUNCTIONARE GARNITURA SST/SWT 50 201100051, TESTE DE FUNCTIONARE
