
Reparatie pompa recirculare agent termic WILO

I.D.: 52435794

Data publicarii	07.12.20	Coduri CPV	50800000-3
-----------------	----------	------------	------------

Pretul estimativ: 1.385,00 RON - 1.385,00 RON

Descriere: Reparatie pompa tip WILO IPL 50 / 150 - 4/2 PN 16, inlocuire kit etansare mecanica, inlocuire rulmenti moto 2 bucr, manopera montare demontare
