

Reparatie Videogastroscoop Pentax MODEL: EG-2990K/ K120471

I.D.: 93416797

Data publicarii 16.02.24 Coduri CPV 50420000-5

Pretul estimativ: 26.206,00 RON - 26.206,00 RON

Descriere: 1 Inlocuire ansamblu de insertie cu tub si canale 2 Reconditionare deflectie cu inlocuire arcuri, cabluri, camasa segment si scripeti 3 Inlocuire conductor de lumina 4 Inlocuire ansamblu tub de alimentare cu canale 5 Inlocuire manson deflectie PIESE DE SCHIMB SI MATERIALE FOLOSITE Nr crt. Cod Denumire Cantitate Pret Unitar(lei) Pret Total(lei) 1 D084-U3030-3 INSERTION FLEXIBLE TUBE/Ansamblu tub de insertie 1 9835 9835 2 D888-U5015 DISTAL END ASSY WITH TUBES/Capat distal cu canale 1 3399 3399 3 D084-SA037 SEGMENT STEEL BRAID/Plasa protectie 1 80 80 4 D084-SA038-1 BENDING RUBBER/Manson flexibil 1 189 189 5 D084-AA039-3 STAYCOIL ASSY/Ansablu ptr cabluri 1 939 939 6 D115-AA042 ANGLE WIRE/Cabluri tractiune 4 102 408 7 D029-SA027 ADJUSTING COLLAR/Bucse ajustoare 4 30 120 8 D009-SA045 STAYCOIL COLLAR/Bucse cuplare 4 30 120 9 D754-SA057-2 ROOT BRACE RUBBER IMP-1/Con de protectie 1 354 354 10 D201-U2165 RL PULLEY ASSY/Ansamblu scripeti RL 1 764 764 11 D201-U2160 UD PULLEY ASSY/Ansamblu scripeti UD 1 764 764 12 D569-U5061-1 LIGHT GUIDE CABLE/Tub de alimentare 2897 2897 13 D888-U5090 LIGHT GUIDE FIBER BUNDLE(LCB)/Cablu fibra de lumina 1 4385 4385 14 D569-AC141 AIR/WATER SUPPLY TUBE LG /Canale Aer/Apa 2 618 618 15 D756-AC161 JET SUPPLY TUBE LG/Canal jet suplimentar 1 291 291 16 D756-AC027 SUCTION CHANNEL LG/Canal de aspiratie 1 793 793 17 Set garnituri etansare, consumabile 1 250 250 TOTAL 26206 LEI TVA 19%