



Servicii de intretinere VW TRANSPORTER

I.D.: 101792600

Data
publicarii 21.08.24

Coduri CPV 50112200-5

Pretul
estimativ: 1.159,41 RON - 1.159,41 RON

Descriere: Servicii de intretinere VW TRANSPORTER ce includ: inlocuire ulei original 504/50700, buson baie ulei, filtru ulei, filtru combustibil, filtru aer, filtru polen, materiale mici, aerisire instalatie combustibil.
