



---

## **reparatie Dacia Duster CL 39 HHS**

I.D.: 50503902

---

Data publicarii	09.10.20	Coduri CPV	50112000-3
-----------------	----------	------------	------------

---

Pretul estimativ:	878,01 RON - 878,01 RON
-------------------	-------------------------

---

Descriere:	inlocuit rulment roata,curea transmisie,furtun turbo si solutie sistem racire=+manopera
------------	---

---