
DEVIZ REPARATIE PLM 5113N

I.D.: 39860796

Data publicarii	15.06.18	Coduri CPV	50000000-5
-----------------	----------	------------	------------

Pretul estimativ: 178,45 RON - 178,45 RON

Descriere: CUTIT TAIAT IARBA 671001554 PLM 5102/5 LA PRETUL DE 66,79, CUREA TRANSMISIE V10X885 PLM5 102/5 LA PRETUL DE 69,72 LEI, MANOPERA 41,94 LEI (conform deviz de reparatie)
