
REPARATII VOLKSWAGEN TRANSPORTER

I.D.: 53514688

Data publicarii	18.01.21	Coduri CPV	50112000-3
-----------------	----------	------------	------------

Pretul estimativ:	2.156,09 RON - 2.156,09 RON
-------------------	-----------------------------

Descriere:	inlocuit etrier spate inlocuire placute frana spate inlocuire cablu rfana de mana inlocuire bucsi bara torsiune spate
------------	---
