
Servicii de reparatii

I.D.: 58102792

Data publicarii	18.06.21	Coduri CPV	50800000-3
-----------------	----------	------------	------------

Pretul estimativ: 1.328,00 RON - 1.328,00 RON

Descriere: Golit instalatie incalzire centrala si inlocuit robineti calorifer ATCP -spate casei Desfundat canal apa pluviala terasa et.2 secretariat inlocuit robinet hidrant at.7 corpA Desfundat canalizare Wc et.3 corpB inlocuit racord flexibil Desfundat lavoare, sifoane pardoseala de la parter-et.VII corp A si B Materiale utilizare adapto15-1/2 int. , mufa alama 1/2 dop radiator1/2 ICMA, racord WC flexibil, silicon sanitar alb, robinet hidrant
