
Servicii de intretinere VW TRANSPORTER

I.D.: 88345629

Data publicarii	17.10.23	Coduri CPV	50112200-5
-----------------	----------	------------	------------

Pretul estimativ: 952,82 RON - 952,82 RON

Descriere: Servicii de reparare si intretinere VW TRANSPORTER ce includ: interval service ce include inlocuire ulei motor 504/50700, buson baie ulei, filtru ulei, filtru aer, filtru polen, filtru combustibil, materiale mici, aerisit instalatie combustibil.
